



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, November 9, 2021	Project Contact:	Brian Clauto
Spread H: Montgomery	AR 276.03 St1233+32-12190 ATWS 1446, 704A, 1216, 1217	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Fellin	g		Clearing/Grubbing		Grading		Trenching	☐ Stringing/Weldin		ging/Welding		
	Lowering/B	Backfilling		Final Grading		Temp. Stabilization		Perm. Stabilization	\boxtimes	□ Dormant			
									Yes	No	N/A		
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							\boxtimes					
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							\boxtimes				
	3.	3. Areas of offsite sediment deposition observed?						\boxtimes					
■ Comments: Inspected the following resources: S-OO11, S-C21 ■ ECD's that have been installed at the resources appeared to be functioning. Routine Maintenance: (72-Hour Deadline from Notification) - Sta. 12201-12207 bare areas require additional stabilization. - Sta. 12233+32 slopes requires re stabilizations Ineffective Controls: (24-Hour Deadline from Notification) Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.													
The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.													
Inspector Signature:													

Tuesday, November 9, 2021

Date:

FIELD INSPECTION PHOTO LOG



Project Name: Mountain Valley Pipeline <u>Date</u>: Tuesday, November 9, 2021

Figure 1: St12233+32 slope requires re stabilization.



Figure 2: St12205 area requires re stabilization.



Figure 3: St12203+85 bare areas requires re stabilization.



Figure 4: Designated crossing S-C21, ECD's are in place.

