

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, November 29, 2022	Project Contact:	Brian Clauto
Spread H: Roanoke	ATWS1227, 1226, 1228 AR RO 281, 282 ST 12730-12760	Weather:	Dry

Roa	anoke	ST 1	2730-12760										
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
☐ Tree Felling			Clearing/Grub	Clearing/Grubbing 🔲 G				Trenching		Strii	nging/Welding		
	Lowering/Backfilling	ing/Backfilling Final Grading Temp. Stabilization Perm. Stabilization						n 🗵 Dormant					
									Yes	No	N/A		
1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?									\boxtimes				
	2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?									\boxtimes			
	3. Areas o	f offsite	sediment depos	sition observ	ed?					\boxtimes			
Routine Maintenance: (72-Hour Deadline from Notification) - St 12740-12748, erosion control blanket requires repair in multiple areas. Ineffective Controls: (24-Hour Deadline from Notification) - N/A Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.													
Deadline: Within 72-Hour of Notification The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.													

Inspector Signature:

Date: Tuesday, November 29, 2022

FIELD INSPECTION PHOTO LOG



Project Name: Mountain Valley Pipeline

Date: Tuesday, November 29, 2022

 Figure 1: Designated crossing S- EF34b, controls remain in place.



 <u>Figure 2</u>: St 12740-12748, ECB requires repair in multiple locations.



Figure 3: Near St 12748, ECB requires repair.



• Figure 4: Designated crossing S- EF33, controls remain in place.

