

COMPLAINT INVESTIGATION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, December 4, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	MVP-RO-282 MVP-RO-283	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☒ Trenching
 ☒ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Resource Crossing

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Background: This investigation was conducted in response to a complaint (IR#: 311693) submitted to PREP on December 03, 2023. The incident description is "water pumps polluting wetlands" occurring on 12/02/2023 at "MVP LOD onto private property". The location is described as "8741 Poor Mountain Rd, Bent Mountain, VA 24059".

Observations:

- Several locations were inspected along access roads RO-282 and RO-283. No dewatering was occurring along RO-282 which is closest to the location provided within the PREP report.
- Three dewatering structures were located from STA 12792+00 to 12807+00.
- The dewatering structure at STA 12804+00 was found to have sediment accumulation within the structure outside of the sediment bag. The source of the sediment within the structure occurred from a previous removal of a full sediment bag. No sediment deposition was found outside of the dewatering structure itself and no sediment was observed discharged from the LOD.
- A corrective action was noted to remove the sediment from within the dewatering structure to prevent the treated water becoming more turbid prior to being discharged as sheet flow to a well vegetated area.

Recommended Corrective Action:

Ineffective Controls: (24-Hour Deadline from Notification)

- STA 12804+00: Remove sediment from within dewatering structure.

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Monday, December 4, 2023

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, December 4, 2023

Figure 1: STA 12804+00– Dewatering structure maintenance needed. Remove sediment from within dewatering structure.



Figure 2: STA 12804+00 – Dewatering structure maintenance needed. Remove sediment from within dewatering structure.

