

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)			
Inspector:	Marshall Willis	Inspection Date:	Thursday, August 14, 2025			
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cory.chalmers@eqt.com brian.clauto@eqt.com			
Spread I: Pittslyvania County	STA 15772+27 - 15834+92 MVP-MLV-AR-35 MVP-PI-338.01 MVP-PI-339	Site Conditions:	Dry			

ACT	ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling		☐ Clearing/Grubbing			Rough Grading		Trenching		Stri	inging/Welding			
	Lowering/Backfilling			Final Grading		Temp. Stabilization	\boxtimes	Perm. Stabilization	ition \square		Other			
									Yes	No	N/A			
	 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? 								\boxtimes					
									\boxtimes					
	3. Areas of offsite sediment deposition observed?								\boxtimes					
	Routin - Ineffec	ents: Inspe ne Maintena N/A ctive Contro N/A ctive Actio	ance (ols (2	4-Hr):	s: S-Kl	.27 and S-C1.								

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Thursday, August 14, 2025



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1

STA 15773+00: Controls in place and functioning properly.



Fig. 2

STA 15792+00: Controls in place and functioning properly.



Fig. 3

STA 15516+00: Controls in place and functioning properly.



Fig. 4

STA 15834+00: Controls in place and functioning properly.

