

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, November 12, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13342+67 – 13316+13	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☒ Trenching
 ☒ Stringing/Welding
☒ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☐ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-GH9, S-GH11, S-GH14 and S-GH15.

Ineffective Controls: (24-Hour Deadline from Notification)

- STA 13337+00: Bridge underlayment repair needed.
- STA 13337+00: Bridge wattle cleanout needed.
- STA 13337+00: P1 undermined.
- STA 13337+00: Sediment impacting resource S-GH9.
- STA 13336+92: P1 undermined.
- STA 13333+96: SSF undermined.
- STA 13333+59: Sump cleanout needed.
- STA 13334+17: Sediment impacting resource S-GH11.
- STA 13333+00: Waterbar repair needed.
- STA 13332+23: Sump cleanout needed.
- STA 13332+23: Sediment off ROW.
- STA 13325+75: P1 undermined.
- STA 13325+50: Stream wattle cleanout needed.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, November 12, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, November 12, 2020

Figure 1: STA 13337+00 – Stream S-GH9 bridge underlayment repair needed.



Figure 2: STA 13337+00 – Stream S-GH9 bridge wattle cleanout needed.



Figure 3: STA 13337+00 – P1 undermined.



Figure 4: STA 13337+00 – Sediment impacting stream from S-GH9 bridge.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, November 12, 2020

Figure 5: STA 13336+92 – P1 undermined.



Figure 6: STA 13333+96 – SSF undermined.



Figure 7: STA 13333+59 – Sump cleanout needed.



Figure 8: STA 13334+17 – Sediment impacted stream S-GH11 from sump at STA 13333+59.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, November 12, 2020

Figure 9: STA 13333+00 – Waterbar overtopped, repair needed.



Figure 10: STA 13332+23 – Sump cleanout needed.



Figure 11: STA 13332+33 – Sediment discharged off ROW from sump at STA 13332+23.



Figure 12: STA 13325+75 – P1 undermined.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, November 12, 2020

Figure 13: **STA 13325+50** – Stream S-GH11 bridge wattle cleanout needed.

