

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, December 2, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14411+04 – 14546+75 MVP-FR-315	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☐ Trench Excavation
 ☐ Pipe Assembly, Testing & Installation
☐ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☒ Other: Dormant

- | | Yes | No | N/A |
|---|--------------------------|-------------------------------------|--------------------------|
| 1 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☐ | ☒ | ☐ |
| 2 Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3 Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-GH36, S-GH37, S-KL17, S-GH39, S-GH40, S-GH40, S-GH47, S-G22, S-G21, S-G20, S-G23, S-G18 and S-G27.

STA 14545+00: End-treatment bypassed.
 STA 14510+00: CFS maintenance needed.
 STA 14504+50: Erosion matting needed on slope.
 STA 14486+00: Stabilize slope CIS Stream S-G22.

Recommended Corrective Action: Maintain and install all controls per the approved plans and PSS&S.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 12/02/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, December 2, 2019

Fig. 1: **STA 14545+00** – Discharge bypassing CFS end-treatment. Maintenance needed.



Fig. 2: **STA 14510+00** – CFS undermined. Maintenance needed.



Fig. 3: **STA 14504+50** – Erosion control matting needed on steep slope.



Fig. 4: **STA 14486+00** – Stabilization needed on CIS slope of Stream S-G22.

