

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, July 15, 2019	Project Contact:	Brian Clauto
Spread H: Franklin County	STA 13258+74 – 13262+66 STA 13060+00 – 13070+00 MVP-FR-293.01/290 ATWS 344/1055	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☒ Trench Excavation
 ☒ Pipe Assembly, Testing & Installation
☐ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☒ Other: Conventional Bore Site

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-II4, W-II4, S-G26 and S-G27.

Inspection of conventional bore site under stream S-II4 (STA 13260+75) at Flanders Road (MVP-FR-293.01) and conventional bore site under streams S-G27 and S-G27 at approx. STA 13062+00.

- STA 13063+10: (S-G27) Re-establish and stabilize 50' buffer zone.
- ATWS 344: Repair CFS end-treatment.
- ATWS 344: Repair CFS end-treatment and sump.
- STA 13064+82: Repair P1.
- STA 13063+64: Repair P1.

Recommended Corrective Action: Maintain and install all controls per the approved plan and specs.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 07/15/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, July 15, 2019

Fig. 1: **Stream S-II4** – GAS borepit for S-II4. Pumps have secondary containment. Trench dewatering to sediment bag inside dewatering structure.

☉ 226°SW (T) ☉ 37°6'56"N, 80°3'35"W ±16.4ft ▲ 1474ft



Fig. 2: **STA 13262+25** – Secondary containment structures intact and functioning as designed.

☉ 277°W (T) ☉ 37°6'56"N, 80°3'35"W ±16.4ft ▲ 1473ft



Fig. 3: **ATWS 1055** – Dewatering structure for GAS of conventional bore pit. Sediment bags are clean, filter structure intact and dewatering to stabilized area.

☉ 245°SW (T) ☉ 37°6'54"N, 80°3'34"W ±16.4ft ▲ 1455ft



Fig. 4: **STA 13262+25** – Secondary containment structures intact and functioning as designed.

☉ 26°NE (T) ☉ 37°6'56"N, 80°3'35"W ±16.4ft ▲ 1474ft



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, July 15, 2019

Fig. 5: **Stream S-G26** – Dewatering structure for CIS of conventional bore pit. Sediment bags functioning inside de-watering structure.



Fig. 6: **Stream S-G27** – Re-establish and stabilize 50' buffer needed for S-G27.



Fig. 7: **ATWS 344** – CFS repairs needed.



Fig. 8: **ATWS 344** – CFS repairs needed. Sump inadequate sizing.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, July 15, 2019

Fig. 9: **STA 13064+82** – P1 in repair needed.



Fig. 10: **STA 13063+64** – P1 in repair needed.

