

FIELD INSPECTION REPORT

| | | | |
|-----------------------------|---------------------------------------|------------------|-----------------------------|
| Project Name: | Mountain Valley Pipeline | Inspector: | Marshall Willis |
| Inspection Date: | Tuesday, August 10, 2021 | Project Contact: | Brian Clauto, Cory Chalmers |
| Spread H: Roanoke County | STA 12910+76 – 12923+66 MVP-RO-286 | Weather: | Dry |

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☒ Clearing/Grubbing
 ☒ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☐ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, August 10, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, August 10, 2021

Figure 1: MVP-RO-286 – Controls in place and functioning properly.

BRG: 107°E (T) **LAT:** 37.144904 **LON:** -80.135592 ±16ft **ALT:** 2642ft



Figure 2: MVP-RO-286 – Controls in place and functioning properly.

BRG: 149°SE (T) **LAT:** 37.144697 **LON:** -80.135278 ±16ft **ALT:** 2670ft



Figure 3: STA 12916+00 – Controls in place and functioning properly.

BRG: 173°S (T) **LAT:** 37.144528 **LON:** -80.137423 ±32ft **ALT:** 2716ft



Figure 4: STA 12923+00 – Controls in place and functioning properly.

BRG: 34°NE (T) **LAT:** 37.143195 **LON:** -80.138260 ±16ft **ALT:** 2656ft

