

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, August 9, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12776+03 – 12796+50 STA 12690+43 – 12703+08 MVP-RO-282/280	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|--|--|--|---|--|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☒ Grading | ☒ Trenching | ☐ Stringing/Welding |
| ☒ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☐ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-EF32, S-EF33, S-IJ82 and W-IJ94-PEM.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Monday, August 9, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, August 9, 2021

Figure 1: STA 12777+00 – Controls in place and functioning properly.

BRG: 168°S (T) LAT: 37.178820 LON: -80.140744 ±16ft ALT: 2808ft



Figure 2: STA 12780+00 – Controls in place and functioning properly.

BRG: 160°S (T) LAT: 37.174035 LON: -80.139255 ±16ft ALT: 2828ft



Figure 3: Stream S-IJ82 – Controls in place and functioning properly around stream S-IJ82.

BRG: 217°SW (T) LAT: 37.170710 LON: -80.138124 ±16ft ALT: 2703ft



Figure 4: STA 12795+00 – Controls in place and functioning properly. Buffer established around S-IJ82.

BRG: 354°N (T) LAT: 37.170317 LON: -80.138184 ±16ft ALT: 2703ft

