

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, August 4, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13996+00 – 14009+81 MVP-FR-306.03/.02 MVP-MLV-AR-32 STA-14233+12 – 14250+00	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
☒ Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-KL36, S-KL38, S-C19 and S-F11.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Wednesday, August 4, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, August 4, 2021

Figure 1: STA 14002+00 – Controls in place and functioning properly.

BRG: 26°NE (T) **LAT:** 37.053878 **LON:** -79.892990 ±9432ft **ALT:** 1091ft



14002

Figure 2: Stream S-C19 – Controls in place and functioning properly around Magodee Creek crossing.

BRG: 267°W (T) **LAT:** 37.055091 **LON:** -79.829774 ±16ft **ALT:** 870ft



S-C19

Figure 3: Stream S-F11 – Controls in place and functioning properly around Blackwater River crossing.

BRG: 123°SE (T) **LAT:** 37.052850 **LON:** -79.826178 ±16ft **ALT:** 863ft



S-F11

Figure 4: STA 14006+00 – Controls in place and functioning properly.

BRG: 12°N (T) **LAT:** 37.055506 **LON:** -79.883859 ±16ft **ALT:** 1089ft



14006