

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, July 29, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13342+40 – 13415+51	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-IJ2-PSS, S-IJ3, W-IJ1, S-IJ2, S-IJ1, S-RR11, S-RR08 and S-RR09.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 13404+00 to 13387+64: Re-stabilization needed.
- STA 13383+00 to 13379+00: Re-stabilization needed.
- STA 13373+00 to 13371+00: Re-stabilization needed.
- STA 13345+00: Re-stabilization needed around CWD crossing.
- STA 13344+00: Re-stabilization needed.

Ineffective Controls: (24-Hour Deadline from Notification)

- STA 13361+00: CFS clean out needed.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Various - See Comments

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Thursday, July 29, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, July 29, 2021

Figure 1: STA 13404+00 to 13387+64 – Re-stabilization needed.

BRG: 17°N (T) LAT: 37.095747 LON: -80.031861 ±16ft ALT: 1725ft



Restabilize 72hr

13397

Figure 2: STA 13383+00 to 13379+00 – Re-stabilization needed.

BRG: 344°N (T) LAT: 37.099361 LON: -80.033713 ±16ft ALT: 1702ft



Restabilize 72hr

13385

Figure 3: STA 13373+00 to 13371+00 – Re-stabilization needed.

BRG: 201°S (T) LAT: 37.101559 LON: -80.035589 ±16ft ALT: 1766ft



Restabilize 72hr

13371

Figure 4: STA 13361+00 – CFS clean out needed.

BRG: 212°SW (T) LAT: 37.100977 LON: -80.039402 ±1171ft ALT: 1493ft



CFS maint 24

13361

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, July 29, 2021

Figure 5: STA 13345+00 – Re-stabilization needed.

BRG: 139°SE (T) LAT: 37.103796 LON: -80.042737 ±16ft ALT: 1527ft



Restabilize 72

13345

Figure 6: STA 13344+00 – Re-stabilization needed.

BRG: 232°SW (T) LAT: 37.103903 LON: -80.042955 ±16ft ALT: 1547ft



Restabilize 72

13344