

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Friday, July 23, 2021	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread H: Roanoke County</b>	STA 12964+64 – 12980+00 STA 12945+00 – 12958+54 MVP-RO-288/287/286	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- |   |  |  |  |   |
|---|--|--|--|---|
| <input type="checkbox"/> Tree Felling         | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading             | <input type="checkbox"/> Trenching           | <input type="checkbox"/> Stringing/Welding  |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:** Inspected the following resources: S-SK4, S-Y7 and S-Y8.

**Recommended Corrective Action:** N/A

**Deadline:** Various - See Comments

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** Marshall Willis

**Date:** Friday, July 23, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Friday, July 23, 2021

**Figure 1: STA 12972+00** – Controls in place and functioning properly.  
BRG: 337°NW (T) LAT: 37.130631 LON: -80.137332 ±98ft ALT: 2709ft



**Figure 2: STA 12957+00** – Controls in place and functioning properly.  
BRG: 185°S (T) LAT: 37.134656 LON: -80.137381 ±32ft ALT: 2636ft



**Figure 3: STA 12950+00** – Controls in place and functioning properly. Area stabilized with straw and erosion control matting.  
BRG: 318°NW (T) LAT: 37.136478 LON: -80.138581 ±32ft ALT: 2726ft



**Figure 4: MVP-RO-286** – Controls in place and functioning properly along MVP-RO-286.  
BRG: 122°SE (T) LAT: 37.144928 LON: -80.135617 ±16ft ALT: 2715ft

