



		I	
Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, July 21, 2021	Project Contact:	Brian Clauto
Spread H: Franklin	AR FR291, FR-292.01 ATWS1482, 1483, 1251, 1248, 1248A, 1410, 1249 St 13118-13194	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	☐ Tree Felling		☐ Clearing/Grubbing		\boxtimes	Grading		Trenching	\boxtimes	Stri	inging/Welding		
\boxtimes	Lowering/E	Backfilling		Final Grading		Temp. Stabilization		Perm. Stabilization	n 🗌 Dormant		rmant		
									Yes	No	N/A		
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								\boxtimes				
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								\boxtimes				
	3.	Areas of of	fsite	sediment deposition	observe	d?				\boxtimes			
■ <u>Comments:</u> Inspected the following resources: S-C12, S-EF17, S-D11, S-D13, S-D17 ■ <u>ECD's were in place and functioning above the designated crossing for active construction.</u> Routine Maintenance: (<u>72-Hour Deadline from Notification</u>) - St 13120 uncontained trash - St 13120 inlet protection requires sediment removal - St 13132 uncontained trash - St 13135 uncontained trash Ineffective Controls: (<u>24-Hour Deadline from Notification</u>) - N/A													

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Wednesday, July 21, 2021

FIELD INSPECTION PHOTO LOG



Project Name: Mountain Valley Pipeline Date: Wednesday, July 21, 2021

Figure 1: St13120 Uncontained trash

North East Elevation

© 207°SW (T) © 37°7′19"N, 80°5′36"W ±16ft ▲ 2310ft

Figure 2: Near St 13120 inlet protection requires maintenance







