

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, July 21, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13115+97 – 13195+79 MVP-FR-291 MVP-FR-291.02	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|--|--|--|---|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☒ Grading | ☒ Trenching | ☒ Stringing/Welding |
| ☒ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☐ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-D17, S-D13 and S-D11.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Wednesday, July 21, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, July 21, 2021

Figure 1: STA 13119+00 – Controls in place and functioning properly.

BRG: 113°SE (T) **LAT:** 37.121959 **LON:** -80.094961 ±9363ft **ALT:** 2579ft



Figure 2: STA 13126+00 – Controls in place and functioning properly.

BRG: 97°E (T) **LAT:** 37.121809 **LON:** -80.092558 ±32ft **ALT:** 2148ft



Figure 3: STA 13133+00 – Controls in place and functioning properly.

BRG: 93°E (T) **LAT:** 37.121529 **LON:** -80.090158 ±32ft **ALT:** 1869ft



Figure 4: STA 13176+00 – Controls in place and functioning properly.

BRG: 82°E (T) **LAT:** 37.125586 **LON:** -80.080653 ±16ft **ALT:** 1623ft

