

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, July 16, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12119+17 – 12190+85 MVP-MN-273/274	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-C36, W-C12, W-C11, S-MM31, S-C29, W-C6, W-C5, S-C25 and S-C24.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 12130+89: Re-stabilization needed.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Friday, July 16, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, July 16, 2021

Figure 1: STA 12130+89 – Re-stabilization needed.

BRG: 315°NW (T) **LAT:** 37.256554 **LON:** -80.278522 ±16ft **ALT:** 1385ft



Figure 2: STA 12140+00 – Controls in place and functioning properly.

BRG: 104°E (T) **LAT:** 37.256076 **LON:** -80.276475 ±16ft **ALT:** 1434ft



Figure 3: STA 12164+00 – Controls in place and functioning properly.

BRG: 91°E (T) **LAT:** 37.252163 **LON:** -80.266371 ±2253ft **ALT:** 1420ft



Figure 4: STA 12184+00 – Controls in place and functioning properly.

BRG: 107°E (T) **LAT:** 37.252758 **LON:** -80.261853 ±16ft **ALT:** 1393ft

