

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, July 14, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12071+80 – 12119+17 MVP-MN-270	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-MM15, S-MM14, S-MM13, S-MM11, S-F15, W-F9-PFO and S-F16A/B.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 12073+00: Re-stabilization needed.
- STA 12078+00: Re-stabilization needed.
- STA 12098+40: Repair SSF.
- STA 12098+40 to 120100: Re-stabilization needed.
- STA 12116+00: Re-Stabilization needed.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Wednesday, July 14, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, July 14, 2021

Figure 1: STA 12073+00 – Re-stabilization needed.

BRG: 283°W (T) LAT: 37.258575 LON: -80.297055 ±32ft ALT: 1801ft



Figure 2: STA 12078+00 – Re-stabilization needed.

BRG: 111°E (T) LAT: 37.258791 LON: -80.296066 ±32ft ALT: 1876ft



Figure 3: STA 12098+40 – Repair SSF.

BRG: 324°NW (T) LAT: 37.258225 LON: -80.289077 ±32ft ALT: 1536ft



Figure 4: STA 12098+40 to 12100+00 – Re-stabilization needed.

BRG: 284°W (T) LAT: 37.258284 LON: -80.288541 ±16ft ALT: 1523ft



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, July 14, 2021

Figure 5: STA 12116+00 – Re-stabilization needed.

BRG: 128°SE (T) LAT: 37.257603 LON: -80.283468 ±16ft ALT: 1466ft

