

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Wednesday, July 7, 2021	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread H: Franklin County</b>	STA 13140+00 – 13195+50 MVP-FR-292 MVP-FR-292.01	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Restoration     
  Temp. Stabilization     
  Perm. Stabilization     
  Dormant

- |    |   | Yes                      | No                                  | N/A                      |
|----|---|--------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-D13, S-D11 and S-D10.

**Ineffective Controls:** (24-Hour Deadline from Notification)

- STA 13159+13: No outlet provided for ROW Diversion (RWD) per VESCH 3.11.
- STA 13187+00: P1 undermined.

**Recommended Corrective Action:** Provide waterbar outlet with sump and end treatment at RWD at STA 13159+13 and at all of the locations where RWDs cross the ROW.

**Deadline:** Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** Wednesday, July 7, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, July 7, 2021

**Figure 1: STA 13159+00** – No outlet provided for RWD.

BRG: 198°S (T) LAT: 37.124426 LON: -80.085483 ±16ft ALT: 1646ft



**Figure 2: STA 13163+00** – Controls in place and functioning properly.

BRG: 86°E (T) LAT: 37.125364 LON: -80.085007 ±98ft ALT: 1739ft



**Figure 3: STA 13174+00** – Controls in place and functioning properly.

BRG: 262°W (T) LAT: 37.051904 LON: -80.043841 ±19242ft ALT: 1733ft



**Figure 4: STA 13187+00** – P1 undermined.

BRG: 98°E (T) LAT: 37.124888 LON: -80.076938 ±32ft ALT: 1472ft

