

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Friday, July 2, 2021	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread H: Franklin County</b>	STA 13410+00 – 13415+50 STA 13337+13 – 13348+50 STA 13316+13 – 13306+16 STA 13265+00 – 13263+50	<b>Weather:</b>	Wet

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling     
 ☐ Clearing/Grubbing     
 ☐ Grading     
 ☐ Trenching     
 ☐ Stringing/Welding  
☐ Lowering/Backfilling     
 ☐ Final Restoration     
 ☐ Temp. Stabilization     
 ☐ Perm. Stabilization     
☒ Dormant

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-IJ1, S-IJ3, S-IJ2, W-IJ1, W-IJ2, S-RR08, S-GH9, S-GH78 and S-II4.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** Marshall Willis

**Date:** Friday, July 2, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Friday, July 2, 2021

**Figure 1: STA 13413+00** – Controls in place and functioning properly.

**BRG:** 281°W (T) **LAT:** 37.093018 **LON:** -80.027798 ±16ft **ALT:** 1416ft



**Figure 2: STA 13342+00** – Controls in place and functioning properly.

**BRG:** 291°W (T) **LAT:** 37.104034 **LON:** -80.043760 ±32ft **ALT:** 1429ft



**Figure 3: STA 13315+00** – Controls in place and functioning properly.

**BRG:** 239°SW (T) **LAT:** 37.106548 **LON:** -80.052370 ±16ft **ALT:** 1396ft



**Figure 4: STA 13260+00** – Controls in place and functioning properly.

**BRG:** 266°W (T) **LAT:** 37.115595 **LON:** -80.060622 ±16ft **ALT:** 1455ft

