

## FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, July 1, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14062+17 – 14132+30 MVP-FR-309.05/309	Weather:	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding  
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-EF48, W-EF51, S-KL61 and S-KL41.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Thursday, July 1, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Thursday, July 1, 2021

**Figure 1: STA 14063+00** – Controls in place and functioning properly.

**BRG:** 166°S (T) **LAT:** 37.065406 **LON:** -79.875091 ±16ft **ALT:** 1197ft



**Figure 2: STA 14077+00** – Controls in place and functioning properly.

**BRG:** 303°NW (T) **LAT:** 37.064530 **LON:** -79.871038 ±16ft **ALT:** 1197ft



**Figure 3: STA 14102+00** – Controls in place and functioning properly.

**BRG:** 78°E (T) **LAT:** 37.062021 **LON:** -79.863557 ±16ft **ALT:** 1059ft



**Figure 4: STA 14109+00** – Controls in place and functioning properly.

**BRG:** 225°SW (T) **LAT:** 37.062948 **LON:** -79.861452 ±32ft **ALT:** 1061ft

