

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Tuesday, June 29, 2021	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread H:</b> Roanoke County Franklin County	STA 12724+88 – 12742+00 STA 13138+00 – 13145+00 MVP-RO-281/281.01 MVP-FR-291/292	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- |   |   |  |  |  |
|---|---|--|--|--|
| <input type="checkbox"/> Tree Felling         | <input checked="" type="checkbox"/> Clearing/Grubbing | <input checked="" type="checkbox"/> Grading  | <input type="checkbox"/> Trenching           | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration            | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input type="checkbox"/> Dormant           |

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-EF52, S-D17 and S-D14.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** Marshall Willis

**Date:** Tuesday, June 29, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, June 29, 2021

**Figure 1: STA 12729+00** – Controls in place and functioning properly.

**BRG:** 233°SW (T) **LAT:** 37.185072 **LON:** -80.148623 ±164ft **ALT:** 3400ft



**Figure 2: MVP-RO-281.01** – Controls in place and functioning properly.

**BRG:** 98°E (T) **LAT:** 37.184082 **LON:** -80.149251 ±32ft **ALT:** 3249ft



**Figure 3: STA 12740+00** – Controls in place and functioning properly.

**BRG:** 183°S (T) **LAT:** 37.182419 **LON:** -80.149371 ±98ft **ALT:** 3082ft



**Figure 4: STA 131378+00** – Controls in place and functioning properly.

**BRG:** 269°W (T) **LAT:** 37.120850 **LON:** -80.087100 ±5787ft **ALT:** 1696ft

