

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Friday, August 27, 2021	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread H: Montgomery County</b>	STA 12420+32 – 12443+00 MVP-RO-279 MVP-RO-279.02	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Restoration     
  Temp. Stabilization     
  Perm. Stabilization     
 Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-NN16.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** Friday, August 27, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Friday, August 27, 2021

**Figure 1: Stream S-NN16** – Controls in place and functioning properly around Roanoke River.

**BRG:** 37°NE (T) **LAT:** 37.233281 **LON:** -80.198082 ±16ft **ALT:** 1172ft



**Figure 2: STA 12926+00** – Controls in place and functioning properly.

**BRG:** 2°N (T) **LAT:** 37.235755 **LON:** -80.198566 ±318ft **ALT:** 1216ft



**Figure 3: STA 12437+00** – Controls in place and functioning properly.

**BRG:** 228°SW (T) **LAT:** 37.233145 **LON:** -80.198342 ±32ft **ALT:** 1186ft



**Figure 4: STA 12446+00** – Controls in place and functioning properly.

**BRG:** 237°SW (T) **LAT:** 37.232509 **LON:** -80.198915 ±32ft **ALT:** 1226ft

