

## FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, August 26, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12888+32 – 12928+00 MVP-RO-286	Weather:	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☒ Clearing/Grubbing
 ☒ Grading
 ☐ Trenching
 ☐ Stringing/Welding  
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☐ Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-EF44, W-EF44, S-IJ12, W-MN7-PEM, W-KL51-PSS and S-KL55.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Thursday, August 26, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Thursday, August 26, 2021

**Figure 1: Stream S-EF44** – Controls in place and functioning properly.

BRG: 101°E (T) LAT: 37.142986 LON: -80.138512 ±16ft ALT: 2672ft



**Figure 2: STA 12926+00** – Controls in place and functioning properly.

BRG: 145°SE (T) LAT: 37.142222 LON: -80.129965 ±32089ft ALT: 2663ft



**Figure 3: Stream S-IJ12** – Controls in place and functioning properly.

BRG: 83°E (T) LAT: 37.148244 LON: -80.133947 ±32ft ALT: 2642ft



**Figure 4: STA 12896+00** – Controls in place and functioning properly.

BRG: 191°S (T) LAT: 37.148286 LON: -80.134013 ±16ft ALT: 2641ft

