

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, September 7, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County Montgomery County	STA 13141+61 – 13195+79 STA 12119+17 – 12140+00 MVP-FR-292/292.01 MVP-MN-272	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☒ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☒ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-D14, S-D13, S-D12, S-D11, W-C6, S-C29, S-MM31, S-C36, W-C12 and W-C11.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Tuesday, September 7, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, September 7, 2021

Figure 1: STA 13165+00 – Controls in place and functioning properly.

BRG: 52°NE (T) LAT: 37.125248 LON: -80.084510 ±16ft ALT: 1734ft



Figure 2: STA 13189+00 – Controls in place and functioning properly. Area stabilized with erosion matting.

BRG: 293°W (T) LAT: 37.152432 LON: -79.992441 ±17818ft ALT: 1510ft



Figure 3: STA 12140+00 – Controls in place and functioning properly.

BRG: 116°SE (T) LAT: 37.257446 LON: -80.276183 ±541ft ALT: 1407ft



Figure 4: STA 12126+00 – Controls in place and functioning properly. Area stabilized with straw..

BRG: 108°E (T) LAT: 37.257371 LON: -80.279451 ±541ft ALT: 1415ft

