

## FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, September 1, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County Franklin County	STA 13145+00 – 13132+00 STA 12724+00 – 12744+00 MVP-FR-292 MVP-RO-281/281.02	Weather:	Rainy

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding  
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: N/A.

**Routine Maintenance:** (72-Hour Deadline from Notification)

- MVP-RO-281 (ATWS 1536): Trash/debris clean up.

**Recommended Corrective Action:** Maintain and install all controls per the approved PSS&S.

**Deadline:** Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Wednesday, September 1, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, September 1, 2021

**Figure 1: MVP-RO-281 (ATWS 1356) – Clean up trash/debris.**

BRG: 115°SE (T) LAT: 37.185238 LON: -80.148131 ±16ft ALT: 3332ft



**Figure 2: STA 13142+00 – Controls in place and functioning properly. Area stabilized with erosion matting.**

BRG: 123°SE (T) LAT: 37.121373 LON: -80.086667 ±16ft ALT: 1613ft



**Figure 3: STA 12729+00 – Controls in place and functioning properly. Area stabilized with erosion matting.**

BRG: 176°S (T) LAT: 37.168452 LON: -80.139086 ±31522ft ALT: 2610ft



**Figure 4: Stream S-EF55 – Controls in place and functioning properly. Area stabilized with erosion matting.**

BRG: 157°SE (T) LAT: 37.181751 LON: -80.140977 ±14363ft ALT: 2868ft

