

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, October 15, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12150+00 – 12200+00 MVP-MN-273/274/275	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-C25, S-C24, S-C21 and S-OO11.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Friday, October 15, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, October 15, 2021

Figure 1: STA 12154+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 96°E (T) LAT: 37.254865 LON: -80.271101 ±32ft ALT: 1542ft



Figure 2: STA 12160+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 112°E (T) LAT: 37.237022 LON: -80.260660 ±6463ft ALT: 1553ft



Figure 3: STA 12172+00 – Controls in place and functioning properly. Area stabilized with straw.
BRG: 104°E (T) LAT: 37.253976 LON: -80.265243 ±32ft ALT: 1423ft



Figure 4: STA 12183+00 – Controls in place and functioning properly. Area stabilized with straw.
BRG: 101°E (T) LAT: 37.252721 LON: -80.261836 ±16ft ALT: 1366ft

