

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, October 14, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13135+00 – 13197+50 MVP-FR-292/292.01	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☒ Lowering/Backfilling
 ☐ Final Restoration
 ☒ Temp. Stabilization
 ☐ Perm. Stabilization
 ☐ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: D17, S-D14, S-D13, S-D11, S-D8 and S-D10.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, October 14, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, October 14, 2021

Figure 1: STA 13149+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 345°N (T) LAT: 0.000000 LON: 0.000000 ALT: 0ft



Figure 2: STA 13158+00 – Controls in place and functioning properly. Area stabilized with erosion matting.

BRG: 47°NE (T) LAT: 37.124617 LON: -80.085487 ±98ft ALT: 1650ft



Figure 3: STA 13163+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 68°NE (T) LAT: 37.124859 LON: -80.084644 ±32ft ALT: 1693ft



Figure 4: STA 13186+00 – Controls in place and functioning properly. Area stabilized with erosion matting.

BRG: 124°SE (T) LAT: 37.122709 LON: -80.076578 ±16420ft ALT: 1638ft

