

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, October 12, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12866+36 – 12915+00 MVP-RO-286	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☒ Temp. Stabilization
 ☐ Perm. Stabilization
 ☐ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-IJ12, W-MN7, W-KL51-PSS, S-KL55, W-KL49-PEM, W-KL50 and W-KL48-PSS-1.

Ineffective Controls: (24-Hour Deadline from Notification)

- STA 12909+00: Stabilize area of overshoot along LOD.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Tuesday, October 12, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, October 12, 2021

Figure 1: STA 12909+00 – Stabilize area of overshoot along LOD.

BRG: 231°SW (T) LAT: 37.146022 LON: -80.136891 ±16ft ALT: 2821ft



Figure 2: STA 12906+00 – Controls in place and functioning properly. Area stabilized with erosion matting.

BRG: 65°NE (T) LAT: 37.146492 LON: -80.135966 ±98ft ALT: 2701ft



Figure 3: STA 12890+00 – Controls in place and functioning properly. Area stabilized with erosion matting.

BRG: 35°NE (T) LAT: 37.149723 LON: -80.132848 ±16ft ALT: 2652ft



Figure 4: STA 12871+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 172°S (T) LAT: 37.153843 LON: -80.129682 ±16ft ALT: 2622ft

