

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, October 7, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12910+00 – 12938+00 MVP-RO-286	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☒ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-EF44 and W-EF44.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, October 7, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, October 7, 2021

Figure 1: MVP-RO-286 – Controls in place and functioning properly along access road.
BRG: 267°W (T) LAT: 37.144853 LON: -80.135831 ±16ft ALT: 2697ft



Figure 2: STA 12916+00 – Controls in place and functioning properly. Area stabilized with straw.
BRG: 148°SE (T) LAT: 37.144511 LON: -80.137618 ±16ft ALT: 2689ft



Figure 3: STA 12923+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 188°S (T) LAT: 37.143462 LON: -80.138072 ±3776ft ALT: 2676ft



Figure 4: STA 12929+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 2°N (T) LAT: 37.141357 LON: -80.138884 ±32ft ALT: 2681ft

