

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, October 4, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13342+67 – 13372+00	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-RR08, S-RR09 and S-RR11.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 13370+00: CFS maintenance needed.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Monday, October 4, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, October 4, 2021

Figure 1: STA 13343+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 116°SE (T) LAT: 37.103922 LON: -80.043198 ±16ft ALT: 1568ft



Figure 2: STA 13359+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 87°E (T) LAT: 37.100967 LON: -80.039578 ±16ft ALT: 1480ft



Figure 3: STA 13369+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 232°SW (T) LAT: 37.101381 LON: -80.036380 ±16ft ALT: 1744ft



Figure 4: STA 13360+00 – CFS maintenance needed.
BRG: 41°NE (T) LAT: 37.101490 LON: -80.036315 ±16ft ALT: 1706ft

