

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, September 17, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County Roanoke County	STA 12445+86 – 12500+00 STA 12620+00 – 12640+00 MVP-RO-279.01/.02 MVP-MLV-AR-28	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|--|---|---|---|--|
| <input type="checkbox"/> Tree Felling | <input checked="" type="checkbox"/> Clearing/Grubbing | <input checked="" type="checkbox"/> Grading | <input checked="" type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input checked="" type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input checked="" type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input type="checkbox"/> Dormant |

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: W-KL58 and S-CD12b.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Friday, September 17, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, September 17, 2021

Figure 1: STA 12498+00 – Controls in place and functioning properly.

BRG: 356°N (T) LAT: 37.233445 LON: -80.175997 ±7129ft ALT: 1248ft



Figure 2: STA 12501+00 – Controls in place and functioning properly.

BRG: 137°SE (T) LAT: 37.223047 LON: -80.203436 ±10278ft ALT: 1694ft



Figure 3: STA 12632+47 – Controls in place and functioning properly.

BRG: 272°W (T) LAT: 37.244383 LON: -80.168715 ±8477ft ALT: 3447ft



Figure 4: STA 12629+00 – Controls in place and functioning properly.

BRG: 285°W (T) LAT: 37.227661 LON: -80.176137 ±9498ft ALT: 3430ft

