

## FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, September 15, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12866+66 – 12935+00 MVP-RO-286	Weather:	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☒ Grading
 ☐ Trenching
 ☒ Stringing/Welding  
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☒ Temp. Stabilization
 ☐ Perm. Stabilization
 ☐ Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: W-EF46, S-ST9b, W-KL48-PSS-1, W-KL49-PEM, S-KL55, S-IJ12, W-MN7-PEM, S-EF44 and W-EF44.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Wednesday, September 15, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, September 15, 2021

**Figure 1: STA 12873+00** – Controls in place and functioning properly.

BRG: 227°SW (T) LAT: 37.153436 LON: -80.129368 ±16ft ALT: 2615ft



12873

**Figure 2: STA 12881+00** – Controls in place and functioning properly.

BRG: 41°NE (T) LAT: 37.151642 LON: -80.130996 ±16ft ALT: 2626ft



12881

**Figure 3: STA 12895+47** – Controls in place and functioning properly.

BRG: 212°SW (T) LAT: 37.148421 LON: -80.133745 ±16ft ALT: 2617ft



12895+47

**Figure 4: STA 12926+00** – Controls in place and functioning properly.

BRG: 212°SW (T) LAT: 37.142550 LON: -80.138357 ±4622ft ALT: 2623ft



12926