

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, September 13, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13250+00 – 13263+45 STA 12994+02 – 13015+13 MVP-FR-293.01	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-II4.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Monday, September 13, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, September 13, 2021

Figure 1: Stream S-II4 – Controls in place and functioning properly along stream S-II4 crossing.

BRG: 338°N (T) LAT: 37.083708 LON: -80.069665 ±68937ft ALT: 1204ft



Figure 2: STA 13260+00 – Controls in place and functioning properly.

BRG: 299°NW (T) LAT: 37.115568 LON: -80.060551 ±16ft ALT: 1440ft



Figure 3: STA 13012+00 – Controls in place and functioning properly.

BRG: 329°NW (T) LAT: 37.125841 LON: -80.125448 ±46653ft ALT: 2697ft



Figure 4: STA 12995+00 – Controls in place and functioning properly.

BRG: 104°E (T) LAT: 37.130749 LON: -80.130707 ±3415ft ALT: 2644ft

