

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, September 27, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14062+87 – 14132+00 STA 14171+36 – 14210+00 MVP-FR-309.05 MVP-FR-309	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-G22, S-G23, S-G21, S-G20, S-G18 and S-G17.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Monday, September 27, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, September 27, 2021

Figure 1: STA 14084+00 – Controls in place and functioning properly.

BRG: 106°E (T) **LAT:** 37.064839 **LON:** -79.868916 ±32ft **ALT:** 1148ft



Figure 2: STA 14120+00 – Controls in place and functioning properly.

BRG: 89°E (T) **LAT:** 37.040729 **LON:** -79.858496 ±19081ft **ALT:** 976ft



Figure 3: STA 14127+00 – Controls in place and functioning properly.

BRG: 134°SE (T) **LAT:** 37.062375 **LON:** -79.856412 ±3349ft **ALT:** 1066ft



Figure 4: STA 14199+00 – Controls in place and functioning properly.

BRG: 152°SE (T) **LAT:** 37.060301 **LON:** -79.838388 ±16ft **ALT:** 1000ft

