

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, October 27, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13846+00 – 13865+00 STA 13920+00 – 13946+00 MVP-FR-303.01 MVP-FR-305	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-C16 and S-C17.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Wednesday, October 27, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, October 27, 2021

Figure 1: STA 13855+00 – Controls in place and functioning properly.

BRG: 105°E (T) **LAT:** 37.058685 **LON:** -79.933048 ±15321ft **ALT:** 1124ft



Figure 2: STA 13850+00 – Controls in place and functioning properly.

BRG: 12°N (T) **LAT:** 37.059115 **LON:** -79.921171 ±16ft **ALT:** 1086ft



Figure 3: STA 13940+00 – Controls in place and functioning properly.

BRG: 127°SE (T) **LAT:** 37.050568 **LON:** -79.899698 ±541ft **ALT:** 1138ft



Figure 4: STA 13928+00 – Controls in place and functioning properly.

BRG: 250°W (T) **LAT:** 37.049724 **LON:** -79.904673 ±16ft **ALT:** 1135ft

