

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Tuesday, October 26, 2021	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread I: Franklin County</b>	STA 13415+00 – 13450+00 STA 13541+00 – 13575+00 MVP-FR-293.02	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling     
 ☐ Clearing/Grubbing     
 ☐ Grading     
 ☐ Trenching     
 ☐ Stringing/Welding  
☐ Lowering/Backfilling     
 ☐ Final Restoration     
 ☐ Temp. Stabilization     
 ☐ Perm. Stabilization     
☒ Dormant

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:** Inspected the following resources: S-IJ8, S-II9, S-II11, S-II12, S-GH6 and W-GH2.

**Routine Maintenance:** (72-Hour Deadline from Notification)

- STA 13416+00 to 13420+00: Re-stabilization needed.

**Recommended Corrective Action:** Maintain and install all controls per the approved PSS&S.

**Deadline:** Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** Marshall Willis

**Date:** Tuesday, October 26, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, October 26, 2021

**Figure 1: STA 13416+00 to 13420+00 – Re-stabilization needed.**

BRG: 104°E (T) LAT: 37.092370 LON: -80.026781 ±246ft ALT: 1452ft



**Figure 2: STA 13416+00 to 13420+00 – Re-stabilization needed**

BRG: 326°NW (T) LAT: 37.092198 LON: -80.026447 ±16ft ALT: 1462ft



**Figure 3: STA 13416+00 to 13420+00 – Re-stabilization needed**

BRG: 318°NW (T) LAT: 37.091792 LON: -80.025668 ±16ft ALT: 1489ft



**Figure 4: STA 13555+00 – Controls in place and functioning properly.**

BRG: 254°W (T) LAT: 37.091684 LON: -79.986349 ±16ft ALT: 1329ft

