

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, October 20, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12445+00 – 12544+00 MVP-MN-278.01 MVP-MLV-AR-28	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|---|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☒ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-EF54, S-EF19, W-KL48 and S-CD12b.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Wednesday, October 20, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, October 20, 2021

Figure 1: STA 12521+00 – Controls in place and functioning properly.

BRG: 305°NW (T) **LAT:** 37.215508 **LON:** -80.196946 ±216ft **ALT:** 1773ft



Figure 2: STA 12507+00 – Controls in place and functioning properly. Area stabilized with erosion matting.

BRG: 290°W (T) **LAT:** 37.217211 **LON:** -80.198922 ±1558ft **ALT:** 1925ft



Figure 3: STA 12490+00 – Controls in place and functioning properly. Area being re-stabilized with erosion matting.

BRG: 172°S (T) **LAT:** 37.221466 **LON:** -80.201469 ±98ft **ALT:** 1677ft



Figure 4: STA 12469+00 – Controls in place and functioning properly. Area stabilized with erosion matting and straw.

BRG: 118°SE (T) **LAT:** 37.228899 **LON:** -80.204099 ±16ft **ALT:** 1232ft

