

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Tuesday, October 19, 2021	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread H: Roanoke County</b>	STA 12591+00 – 12638+00 STA 12690+00 – 12704+00 STA 12866+00 – 12915+00	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- |   |   |  |  |   |
|---|---|--|--|---|
| <input type="checkbox"/> Tree Felling         | <input type="checkbox"/> Clearing/Grubbing            | <input type="checkbox"/> Grading             | <input type="checkbox"/> Trenching           | <input type="checkbox"/> Stringing/Welding  |
| <input type="checkbox"/> Lowering/Backfilling | <input checked="" type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:** Inspected the following resources: S-EF46, S-ST9b, W-KL48-PSS-1, W-KL49-PEM, W-KL51-PEM, S-KL56, W-MN7-PEM and S-IJ12.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** Marshall Willis

**Date:** Tuesday, October 19, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, October 19, 2021

**Figure 1: STA 12630+00** – Controls in place and functioning properly. Area stabilized with erosion matting and straw.  
BRG: 323°NW (T) LAT: 37.193329 LON: -80.175997 ±164ft ALT: 3048ft



**Figure 2: STA 12622+00** – Controls in place and functioning properly. Area stabilized with straw.  
BRG: 151°SE (T) LAT: 37.195210 LON: -80.178369 ±98ft ALT: 3432ft



**Figure 3: STA 12691+00** – Controls in place and functioning properly.  
BRG: 132°SE (T) LAT: 37.189642 LON: -80.152830 ±7644ft ALT: 3775ft



**Figure 4: STA 12901+00** – Controls in place and functioning properly. Area stabilized with erosion matting.  
BRG: 30°NE (T) LAT: 37.145966 LON: -80.137374 ±17060ft ALT: 2831ft

