

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, November 3, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13115+97 – 13195+79 MVP-FR-291 MVP-FR-292/292.01	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|---|--|--|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☒ Temp. Stabilization | ☐ Perm. Stabilization | ☐ Dormant |

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-G17, S-G14, S-D13, S-D11 and S-D10.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Wednesday, November 3, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, November 3, 2021

Figure 1: STA 13115+00 – Controls in place and functioning properly. Area stabilized with erosion matting.

BRG: 88°E (T) LAT: 37.121876 LON: -80.095710 ±16ft ALT: 2655ft



Figure 2: STA 13125+00 – Controls in place and functioning properly. Area stabilized with erosion matting.

BRG: 75°E (T) LAT: 37.121855 LON: -80.092488 ±16ft ALT: 2150ft



Figure 3: STA 13158+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 54°NE (T) LAT: 37.090217 LON: -80.060845 ±16420ft ALT: 1593ft



Figure 4: STA 13163+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 58°NE (T) LAT: 37.125263 LON: -80.085003 ±32ft ALT: 1727ft

