

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, December 1, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13260+00 – 13316+13 MVP-FR-293.01	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-II4 and S-GH37.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____



Date: Wednesday, December 1, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, December 1, 2021

Figure 1: STA 13265+00 – Controls in place and functioning properly.
 BRG: 86°E (T) LAT: 36.990646 LON: -80.064500 ±23727ft ALT: 1413ft



13265

Figure 2: STA 13274+00 – Controls in place and functioning properly.
 BRG: 228°SW (T) LAT: 37.114764 LON: -80.056169 ±98ft ALT: 1651ft



13274

Figure 3: STA 13285+00 – Controls in place and functioning properly.
 BRG: 180°S (T) LAT: 37.112478 LON: -80.055949 ±98ft ALT: 1636ft



13285

Figure 4: STA 13305+00 – Controls in place and functioning properly.
 BRG: 9°N (T) LAT: 37.110509 LON: -80.055801 ±4740ft ALT: 1626ft



13305