

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Tuesday, November 23, 2021	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread H: Montgomery County</b>	STA 12001+72 – 12015+00 MVP-MN-268/268.01	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Restoration     
  Temp. Stabilization     
  Perm. Stabilization     
 Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:** Inspected the following resources: S-NN6 and S-G36.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** \_\_\_\_\_



**Date:** Tuesday, November 23, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, November 23, 2021

**Figure 1: Stream S-G36** – Upstream view of the North Fork Roanoke River ROW crossing.  
**BRG:** 149°SE (T) **LAT:** 37.268630 **LON:** -80.314478 ±16ft **ALT:** 1557ft



**Figure 2: Stream S-G36** – Downstream view of the North Fork Roanoke River ROW crossing.  
**BRG:** 242°SW (T) **LAT:** 37.268628 **LON:** -80.314498 ±16ft **ALT:** 1562ft



**Figure 3: STA 12007+78** – Controls in place and functioning properly. Area stabilized.  
**BRG:** 264°W (T) **LAT:** 37.268877 **LON:** -80.314359 ±16ft **ALT:** 1571ft



**Figure 4: MVP-MN-268.01** – Controls in place and functioning properly at S-G36 crossing.  
**BRG:** 132°SE (T) **LAT:** 37.268736 **LON:** -80.313182 ±370ft **ALT:** 1569ft

