

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Wednesday, November 17, 2021	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread I: Franklin County</b>	STA 13784+00 – 13892+45 MVP-FR-300 MVP-FR-303.01	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- |   |  |  |  |   |
|---|--|--|--|---|
| <input type="checkbox"/> Tree Felling         | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading             | <input type="checkbox"/> Trenching           | <input type="checkbox"/> Stringing/Welding  |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:** Inspected the following resources: S-D23, S-D22, S-D20, S-C14, S-C16, S-C17, W-CD6, S-CD6 and W-CD5,.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** Marshall Willis

**Date:** Wednesday, November 17, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, November 17, 2021

**Figure 1: STA 13787+00** – Controls in place and functioning properly.

**BRG:** 81°E (T) **LAT:** 37.070317 **LON:** -79.932076 ±164ft **ALT:** 1260ft



**Figure 2: STA 13804+00** – Controls in place and functioning properly.

**BRG:** 73°E (T) **LAT:** 37.069602 **LON:** -79.940947 ±15682ft **ALT:** 1076ft



**Figure 3: STA 13845+00** – Controls in place and functioning properly.

**BRG:** 179°S (T) **LAT:** 37.061998 **LON:** -79.922721 ±541ft **ALT:** 1120ft



**Figure 4: STA 13877+00** – Controls in place and functioning properly.

**BRG:** 119°SE (T) **LAT:** 37.054846 **LON:** -79.921053 ±10065ft **ALT:** 1034ft

