

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, November 16, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12724+00 – 12776+00 MVP-RO-281 MVP-RO-282	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-EF34b, S-EF55 and S-EF33.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Tuesday, November 16, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, November 16, 2021

Figure 1: STA 12730+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 202°S (T) LAT: 37.181523 LON: -80.137169 ±9038ft ALT: 3357ft



Figure 2: STA 12739+00 – Controls in place and functioning properly. Area stabilized erosion matting.
BRG: 169°S (T) LAT: 37.182701 LON: -80.149594 ±16ft ALT: 3095ft



Figure 3: STA 12755+00 – Controls in place and functioning properly. Area stabilized erosion matting.
BRG: 93°E (T) LAT: 37.180673 LON: -80.134236 ±22913ft ALT: 3068ft



Figure 4: STA 12765+00 – Controls in place and functioning properly. Area stabilized erosion matting.
BRG: 73°E (T) LAT: 37.179265 LON: -80.145367 ±98ft ALT: 3091ft

