

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, November 15, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12007+00 – 12072+00 MVP-MN-268/268.01 MVP-MN-270	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-G36, S-G38, S-G39, S-G40 and S-PP23.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Monday, November 15, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, November 15, 2021

Figure 1: STA 12061+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 319°NW (T) LAT: 37.260993 LON: -80.299663 ±32ft ALT: 2182ft



Figure 2: STA 12053+00 – Controls in place and functioning properly. Area stabilized erosion matting.
BRG: 336°NW (T) LAT: 37.271777 LON: -80.313685 ±921ft ALT: 1679ft



Figure 3: STA 12031+00 – Controls in place and functioning properly. Area stabilized erosion matting.
BRG: 292°W (T) LAT: 37.265060 LON: -80.308525 ±32ft ALT: 1735ft



Figure 4: STA 12016+00 – Controls in place and functioning properly. Area stabilized erosion matting.
BRG: 148°SE (T) LAT: 37.267227 LON: -80.313112 ±16ft ALT: 1649ft

