



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Monday, November 15, 2021	Project Contact:	Brian Clauto
Spread H: Montgomery	AR 276.03 St 12300-12370 ATWS 1374	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	Tree Fellin	g		Clearing/Grubbing		Grading		Trenching	☐ Stringing/Welding		ging/Welding	
	Lowering/E	Backfilling		Final Grading	$\boxtimes$	Temp. Stabilization		Perm. Stabilization	on 🗵 Dormant		nant	
									Yes	No	N/A	
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?						$\boxtimes$					
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?						$\boxtimes$				
	3. Areas of offsite sediment deposition observed?							$\boxtimes$				
■ <u>Comments:</u> Inspected the following resources: N/A  ■ L&S crews were on site installing matting on portions of slopes during the inspection.  Routine Maintenance: (72-Hour Deadline from Notification)  - N/A  Ineffective Controls: (24-Hour Deadline from Notification)  - N/A  Recommended Corrective Action: N/A												
<u>Deadline:</u> N/A  The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.												
Inspector Signature:												

Monday, November 15, 2021

Date:

## FIELD INSPECTION PHOTO LOG



Project Name: Mountain Valley Pipeline <u>Date</u>: Monday, November 15, 2021

Figure 1: St 12300 ECD's are in place.




Figure 2: St 12330 ECD's are in place.




Figure 3: St 12340 ECD's are in place.



Figure 4: St 12367+27 ECD's are in place.

