

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, November 10, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County Franklin County	STA 13162+95 – 13185+40 STA 12915+00 – 12930+00 STA 12760+00 – 12776+00 MVP-FR-292.01 MVP-RO-282 MVP-RO-286	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|-----------------------------------------------|--------------------------------------------|----------------------------------------------|----------------------------------------------|---------------------------------------------|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- | | | Yes | No | N/A |
|----|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |


Comments: Inspected the following resources: W-EF44 and S-EF44.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Wednesday, November 10, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, November 10, 2021

Figure 1: STA 13168+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 63°NE (T) **LAT:** 37.125412 **LON:** -80.083204 ±16ft **ALT:** 1668ft



Figure 2: STA 12916+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 174°S (T) **LAT:** 37.116035 **LON:** -80.134628 ±34081ft **ALT:** 2674ft



Figure 3: STA 12923+50 – Controls in place and functioning properly. Area stabilized erosion matting.

BRG: 214°SW (T) **LAT:** 37.143205 **LON:** -80.138434 ±16ft **ALT:** 2655ft



Figure 4: STA 12771+00 – Controls in place and functioning properly. Area stabilized erosion matting.

BRG: 266°W (T) **LAT:** 37.180389 **LON:** -80.131340 ±6141ft **ALT:** 2678ft

