

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, November 9, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12190+85 – 12285+00 MVP-MN-276.03 MVP-MN-274	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-OO11 and S-C21.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Tuesday, November 9, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, November 9, 2021

Figure 1: STA 12240+00 – Controls in place and functioning properly.

BRG: 60°NE (T) **LAT:** 37.246490 **LON:** -80.232049 ±19993ft **ALT:** 2443ft



Figure 2: STA 12280+00 – Controls in place and functioning properly.

BRG: 289°W (T) **LAT:** 37.127154 **LON:** -80.309302 ±27582ft **ALT:** 1328ft



Figure 3: STA 12209+00 – Controls in place and functioning properly. Area stabilized erosion matting.

BRG: 73°E (T) **LAT:** 37.210261 **LON:** -80.266300 ±29691ft **ALT:** 1572ft



Figure 4: STA 12233+00 – Controls in place and functioning properly. Area stabilized erosion matting.

BRG: 274°W (T) **LAT:** 37.183839 **LON:** -80.287644 ±4681ft **ALT:** 2143ft

