

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, December 9, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15496+70 – 15584+23	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-CC2-PEM, S-CC13, S-CC14, W-MM5, S-MM8, S-CC15, S-CC5, S-CC8, S-CC9, S-CC10, S-MM10 and S-CC11.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, December 9, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, December 9, 2021

Figure 1: STA 15502+00 – Controls in place and functioning properly. Area stabilized with straw
BRG: 97°E (T) LAT: 36.913131 LON: -79.468459 ±11742ft ALT: 918ft



Figure 2: STA 15514+00 – Controls in place and functioning properly. Area stabilized with straw.
BRG: 88°E (T) LAT: 36.904874 LON: -79.470921 ±8415ft ALT: 843ft



Figure 3: STA 15554+00 – Controls in place and functioning properly. Area stabilized with straw
BRG: 98°E (T) LAT: 36.894303 LON: -79.407332 ±12604ft ALT: 789ft



Figure 4: STA 15572+00 – Controls in place and functioning properly. Area stabilized with straw
BRG: 98°E (T) LAT: 36.898317 LON: -79.450577 ±16420ft ALT: 849ft

