

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, December 8, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15296+00 – 15370+83	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-C3, S-C4, W-C1, S-H14 and W-H5.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Wednesday, December 8, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, December 8, 2021

Figure 1: STA 15302+00 – Controls in place and functioning properly. Area stabilized with straw
BRG: 149°SE (T) LAT: 36.931038 LON: -79.531548 ±213ft ALT: 774ft



Figure 2: STA 15327+00 – Controls in place and functioning properly. Area stabilized with straw.
BRG: 121°SE (T) LAT: 36.928286 LON: -79.522008 ±32ft ALT: 707ft



Figure 3: STA 15343+00 – Controls in place and functioning properly. Area stabilized with straw
BRG: 126°SE (T) LAT: 36.918542 LON: -79.531105 ±9708ft ALT: 752ft



Figure 4: STA 15356+00 – Controls in place and functioning properly. Area stabilized with straw
BRG: 97°E (T) LAT: 36.923368 LON: -79.514165 ±16ft ALT: 740ft

