

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, December 7, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13115+97 – 13195+79 MVP-FR-291 MVP-FR-292.01	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|---|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☒ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-G17, S-G14, S-D13, S-D11 and S-D10.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Tuesday, December 7, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, December 7, 2021

Figure 1: STA 13121+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 123°SE (T) LAT: 37.121969 LON: -80.094099 ±32ft ALT: 2410ft



Figure 2: Stream S-D17 – Controls in place and functioning properly.
BRG: 94°E (T) LAT: 37.121680 LON: -80.088925 ±32ft ALT: 1792ft



Figure 3: STA 13163+00 – Controls in place and functioning properly. Area stabilized with straw
BRG: 70°E (T) LAT: 37.124538 LON: -80.085238 ±10912ft ALT: 1693ft



Figure 4: STA 13176+00 – Controls in place and functioning properly. Area stabilized with straw
BRG: 289°W (T) LAT: 37.125434 LON: -80.079235 ±16ft ALT: 1612ft

