

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Tuesday, December 21, 2021	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread I: Franklin County</b>	STA 13778+00 – 13853+50 MVP-FR-300 MVP-FR-302 MVP-FR-300.01	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling     
 ☐ Clearing/Grubbing     
 ☐ Grading     
 ☐ Trenching     
 ☐ Stringing/Welding  
☐ Lowering/Backfilling     
 ☐ Final Restoration     
 ☐ Temp. Stabilization     
 ☐ Perm. Stabilization     
☒ Dormant

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-D23, S-D22, S-D20, S-C14 an S-C16.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** Marshall Willis

**Date:** Tuesday, December 21, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, December 21, 2021

**Figure 1: STA 13853+00** – Controls in place and functioning properly. Area stabilized with straw.  
BRG: 10°N (T) LAT: 37.069374 LON: -79.904958 ±8133ft ALT: 1180ft



**Figure 2: STA 13833+00** – Controls in place and functioning properly. Area stabilized straw.  
BRG: 194°S (T) LAT: 37.064337 LON: -79.921872 ±32ft ALT: 1074ft



**Figure 3: STA 13807+00** – Controls in place and functioning properly. Area stabilized with straw.  
BRG: 262°W (T) LAT: 37.069612 LON: -79.925718 ±16ft ALT: 1115ft



**Figure 4: STA 13784+00** – Controls in place and functioning properly. Area stabilized with straw.  
BRG: 287°W (T) LAT: 37.069237 LON: -79.946694 ±9051ft ALT: 1062ft

